

## BPW6000 and B6000 Blade Update

## Potential issues:

- 1. MAD3250\*\* Islander, MAD3255\*\* Louvre and MAD3260\*\* Sandella DC fans will not program due to the size of these blades.
- 2. FP320\*\*1 Islander and MA7500\*\* Windpointe experience reduced RPM and decreased airflow performance due to the size of these blades.

## Future use:

1. The BPW6000 and B6000 blades will only be marketed as compatible with the MAD3252\*\* Big Island fan until further notice.

We understand the desire to install these blades on our FP320\*\*1 Islander and MA7500 Windpointe fans. If you want to use this setup, please contact Customer Service to discuss the application. We will approach this on a case by case basis in an effort to ensure expectations are met concerning your fan's performance and airflow.











