



BPW6000 and B6000 Blade Update

Potential issues:

1. MAD3250** Islander, MAD3255** Louvre and MAD3260** Sandella DC fans will not program due to the size of these blades.
2. FP320**1 Islander and MA7500** Windpointe experience reduced RPM and decreased airflow performance due to the size of these blades.

Future use:

1. The BPW6000 and B6000 blades will only be marketed as compatible with the MAD3252** Big Island fan until further notice.

We understand the desire to install these blades on our FP320**1 Islander and MA7500 Windpointe fans. If you want to use this setup, please contact Customer Service to discuss the application. We will approach this on a case by case basis in an effort to ensure expectations are met concerning your fan's performance and airflow.